

Exam : HP HP0-429

**Title : Installling & Supporting
Standard HP SAN
Environments**

Version : Demo

Important Note, Please Read Carefully

Other VisualExams products

[All visualexams IT Exam Products](#)

Our products of Offline Testing Engine

Use the offline Testing engine product to practice the questions in an exam environment.

Build a foundation of knowledge which will be useful also after passing the exam.

[visualexams Testing Engine](#)

Latest Version

We are constantly reviewing our products. New material is added and old material is revised. Free updates are available for 90 days after the purchase. You should check your member zone at VisualExams and update 3-4 days before the scheduled exam date.

Here is the procedure to get the latest version:

1. Go to <http://www.visualexams.com/>
2. Log in the **User Center**
3. The latest versions of all purchased products are downloadable from here. Just click the links.

Feedback

If you spot a possible improvement then please let us know. We always interested in improving product quality.

Feedback should be send to Visualexams@hotmail.com. You should include the following: Exam number, version, page number, question number, and your login Account.

Our experts will answer your mail promptly.

Explanations

This product does not include explanations at the moment. If you are interested in providing explanations for this exam, please contact Visualexams@hotmail.com.

Features

- Comprehensive questions with complete details
- Instant Downloadable in PDF form.
- Verified Answers Researched by Industry Experts
- Questions accompanied by exhibits.
- Drag and Drop questions as experienced in the Actual Exams.
- These questions and answers are backed by our GUARANTEE.
- Questions updated on regular basis.
- Like actual certification exams our product is in multiple-choice questions (MCQs)

Commitment to Your Success: At VisualTestExam.com, we are committed to your ongoing success. Our exams and questions are constantly being updated and compared to industry standards.

Want to earn a Microsoft certification like MCSE, MCSE 2003, CCNA, CCNP? Thinking about getting an A+ or CCSP?

A, CCSP or Network+ Certification with less effort and time. You will be astonished at the theoretical and practical knowledge you will acquire in such a short period of time using our Certification Training Products. Our Study material will enable you to pass your Microsoft, Your Cisco and any other certification on the very first attempt.

Guarantee

VisualExams provides the most competitive quality of all exams for the customers, we guarantee your success at the first attempt with only our Certification Question&Answers, if somehow you do not pass the exam at the first time, we will not only arrange FULL REFUND for you, but also provide you another exam of your claim, ABSOLUTELY FREE!

1. Which security mechanism describes hard zoning?

- A. login authentication
- B. access authorization
- C. network authentication
- D. discovery authorization

Answer: B

2. What can cause a changed hardware path to a connected disk after a switch replacement in an HP-UX environment with multiple B-Series switches? (Select two.)

- A. Zoning on the new switch is not configured correctly.
- B. Simple Name Service is not copied to the new switch.
- C. Core switch PID format parameter differs from the old one.
- D. New switch has a domain ID which differs from the old one.
- E. Disk (storage controller port) is connected to a different switch port.

Answer: DE

3. An HAFM (High Availability Fabric Manager) appliance must be shut down for maintenance reasons. Which operations are not interrupted?

- A. logging events
- B. switch monitoring
- C. Fibre Channel traffic
- D. configuration changes

Answer: C

4. You are replacing the active control processor card, CTP2, of an M-series Director switch. Which action is required before removing the CTP?

- A. Shut down CTP2.
- B. Make CTP2 passive.
- C. Power off the switch.
- D. Shut down the switch.

Answer: B

5. You are adding a new switch to an existing environment. How can you avoid fabric segmentation?

- A. Assign unique domain IDs to the switches.
- B. Register all domain IDs in the fabric name service.
- C. Set up trusts between switches with different domain IDs.
- D. Assign the same domain IDs to all switches connected by ISLs.

Answer: A

6. What is the maximum number of addressable ports per B-series switch running in Native Address mode?

- A. 8
- B. 16
- C. 32
- D. 64

Answer: B

7. What is the best method to consolidate C-Series SAN islands into a common infrastructure without compromising availability, manageability and network security?

- A. Zone the SAN.
- B. Configure LSANs.
- C. Implement VSANs.
- D. Link islands with multi-protocol router.

Answer: C

8. Which M-series feature key is required to implement fabric binding and switch binding?

- A. SANtegrity
- B. Open Trunking
- C. FICON management server
- D. open systems management server

Answer: A

9. You add a switch to a B-series fabric. Its IP address is unknown, so you must use the serial port. Which port attributes must be configured in the terminal emulation in addition to 8 bit, no parity, 1 stop bit?

- A. 9600baud, no flow control
- B. 19200baud, no flow control
- C. 9600baud, hardware flow control
- D. 19200baud, hardware flow control

Answer: A

10. To solve a customer problem, a remote login to a recently installed High Availability Fabric Manager appliance is required. The customer does not know the username and password. Which factory default login should be used?

- A. admin / password
- B. Administrator / password
- C. administrator / Password
- D. Administrator / Administrator

Answer: B

11. In the port error statistics of a Fibre Channel switch port where an HBA is connected, you discover a high ENC_IN (encoding error in frame) count. What are possible causes? (Select three.)

- A. HBA
- B. cable
- C. switch
- D. HBA receiver
- E. switch receiver
- F. HBA transmitter
- G. switch transmitter

Answer: BEF

12. An M-series switch is reset to factory default and Open Trunking becomes inoperable. How do you solve the problem?

- A. Reboot the switch.
- B. Power cycle the switch.
- C. Reinstall the feature keys.
- D. Disconnect and reconnect the switch.

Answer: C

13. While executing several switchShow commands on a B-Series switch, you notice that Port 0 remains a G_Port. What is a possible reason?

- A. faulty port connected
- B. faulty NL_Port connected
- C. functional N_Port connected
- D. functional E_Port connected

Answer: A

14. Where do you find information about all working devices connected to the fabric?

- A. Name Server available from every switch
- B. Node List available on the principal switch
- C. Distributed Node Server List available on every switch
- D. configuration documentation available at the customer site

Answer: A

15. Which HP tool is recommended to manage an M-series fabric consisting of Director and Edge switches?

- A. Web Tools
- B. Fabric Manager
- C. Embedded Web Server
- D. High Availability Fabric Manager

Answer: D

Visualexams.com was founded in 2006. The safer,easier way to help you pass any IT Certification exams . We provide high quality IT Certification exams practice questions and answers(Q&A). Especially Adobe, Apple, Citrix, Comptia, EMC, HP, HuaWei, LPI, Nortel, Oracle, SUN, Vmware and so on. And help you pass any IT Certification exams at the first try.

Web site: <http://www.visualexams.com>

You can reach us at any of the email addresses listed below.

E-Mail: [visualexams \(at\) hotmail.Com](mailto:visualexams@hotmail.com)